- 1, - 3.	Work for Property Loc		Dunlass	4806 West Hampton Avenue ☐ Other ☐		
Date:	Property is: Single Fan 2/4/2013	nily 🗹	Duplex	☐ Other ☐		
		—	foty issues	The City of Milwaukee, the Redevelopment Auth	pority and their repres	ontatives
ake no respo	nsibility for problems discovered a	after the insp	ection date	rne City of Milwaukee, the Redevelopment Autrop, or for omissions through error or oversight. The tral Block Grant or HOME programs.		
Exterior (Condition Report					
_ocation	Required Work			Note/Comments		Cost
Site	Landscaping	n/a 🗹	Yes 🗆	Self Help	\$	
	Steps/Handrails	n/a ✓	Yes 🗌		\$	
	Service walks	n/a ✓	Yes		\$	
	Fencing	n/a 🗌	Yes 🗸	remove or repair to code compliance	\$	1,700.00
	Parking	n/a ✓	Yes 🗌		\$	
	Retaining walls	n/a ✓	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗌		\$	
	Other	n/a □	Yes 🗌		\$	
Garage	Singles: repair	n/a □	Yes 🗌		\$	
		. 5	Yes 🗆		\$	
	Shingles: Roof over existing					
	Shingles:Tear off & re-roof	n/a	Yes 🗌		\$	
	Gutters/downspouts	n/a 📙	Yes 🗌		\$	
	Flashing	n/a 📙	Yes		\$	
	Eaves	n/a 🗌	Yes		\$	
	Siding	n/a 🗌	Yes 🗌		\$	
	Doors	n/a 🗌	Yes		\$	
	Windows	n/a 🗌	Yes 🗌		\$	
	Slab	n/a 🗌	Yes 🗌		\$	
	Paint	n/a 🗌	Yes 🗌		\$	
	Electrical	n/a □	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗸	raze or repair to code compliance	\$	4,250.00
Porches	Roof	n/a ☑	Yes 🗌		\$	
	Deck-upper	n/a ✓	Yes 🗌		\$	
	Decklower	n/a 🗌	Yes 🗸	rear porch	\$	640.00
	Steps/handrails	n/a ☑	Yes	·	\$	
	Ceiling	n/a ☑	Yes 🗌		\$	
	Guardrails	n/a ☑	Yes 🗌		\$	
	Structural	n/a ☑	Yes 🗌		\$ \$	
	Giruciurai	11/a 🖺	169		φ	

n/a $\ \square$ Yes $\ \boxdot$ concrete steps $\ @$ front entry

Other

\$

750.00

House

Chimney	n/a ☐ Yes ☑	\$ 400.00
Shingles: repair	n/a ☑ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 6,540.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 756.00
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a ☑ Yes 🗌	\$
Siding	n/a ☐ Yes ☑	\$ 300.00
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 700.00
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 4,030.00
Paint	n/a ☑ Yes □	\$
Foundation	n/a ☑ Yes □	\$
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a 🗌 Yes 🗹 2 basement windows w/vents	\$ 460.00
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

20,526.00

	Unit: Entire unit (single family) Upper unit of duplex	<!--</th--><th></th><th></th><th></th><th>Lower unit of duplex Other</th><th></th><th></th><th></th><th></th>				Lower unit of duplex Other				
Heating	Required Work	/-		.					Φ.	
	Repair/replace boiler	n/a L	_	es_	<u> </u>				\$	
	Repair radiation	n/a 🕓	<u>/</u> \	es_					\$	
	Repair/replace furnace	n/a	<u> </u>	es/	√				\$	3,080.00
	Repair ductwork	n/a	<u> </u>	⁄es	√				\$	400.00
	Replace thermostat	n/a	<u> </u>	⁄es	√				\$	100.00
	Repair/replace grilles	n/a 🕒	/ \	⁄es					\$	
Electrical	Tune boiler/furn. insp ht exchange	€n/a [<u> </u>	⁄es					\$	
Licotrioui	Repair/replace receptacles	n/a [<u> </u>	⁄es	V				\$	300.00
	Repair/replace switches	n/a	<u> </u>	⁄es	√				\$	300.00
	Repair/replace fixtures	n/a 🕒	/ \	⁄es					\$	450.00
	Install outlets and circuits	n/a 🖸	/ \	/es					\$	
	Install outlets and circuits	n/a 🕒	/ Y	⁄es					\$	
	Install outlets and circuits	n/a 🖸	/ \	⁄es					\$	
	Install outlets and circuits	n/a [/ Y	⁄es					 \$	
	Upgrade service	n/a] \	⁄es	4				\$	1,749.00
	Other	n/a [] \	⁄es					\$	
B	Other	n/a [<u> </u>	⁄es					\$	
Plumbing	Repair/replace kitchen sink	n/a 🕒	/ \	⁄es					\$	
	Repair/replace kitchen sink fauce	ın/a 🖸	/ \	/es					\$	
	Repair/replace tub	n/a 🕒	/ Y	⁄es					\$	
	Repair/replace tub faucet	n/a 🖸	/ Y	⁄es					\$	
	Repair/replace toilet	n/a 🖸	7 Y	⁄es					\$	
	Repair/replace lavatory	n/a 🖸	/ Y	⁄es					\$	
	Repair/replace lavatory faucet	n/a 🗔	/ Y	⁄es					\$	
	Repair/replace wash tub	n/a [/ /	⁄es					\$	
	Repair/replace wash tub faucet	n/a 🖸	/ Y	⁄es					\$	
	Unclog piping:	n/a [/ /	⁄es					\$	
	Repair drain/waste/vent piping	n/a [] \	⁄es	7				\$	400.00
	Repair water piping	n/a [\	⁄es	V				\$	400.00
	Repair/replace water heater	n/a		⁄es	V				 \$	1,300.00
	Other	n/a		⁄es				_	 \$	
	Other	n/a [] \	/es					\$	

Windows							
	Replace broken glass	n/a ☑	Υe	s 🗌		\$	
	Repair or replace sash	n/a [√	Υe	s 🗌		\$	
Doors	Repair or replace doors	n/a	Ye	s 🗸		\$	760.00
	Repair or repl. locks/latches	n/a	Υe	s 🗸	Self Help	\$	220.00
Walls/Ceilin	gs Repair or repl. @ defective	n/a [Υe	s 🗸		\$	500.00
Paint	Repair or repl. @ defective	n/a [l Ye	s 🗸		\$	400.00
Fire Safety						<u> </u>	
riie Salety	Install smoke/CO alarm:bsmt.	n/a	Υe	s 🗸	Self Help	\$	50.00
	Install smoke/CO alarm: 1st flr.	n/a	Υe	s 🗸	Self Help	\$	200.00
	Install smoke/CO alarm: 2nd flr.	n/a ☑	Υe	s 🗌	Self Help	\$	
Handrails	Repair/replace defective	n/a [Ye	s 🗸	Self Help	\$	124.00
Stairs	Repair defective	n/a	Ye	s 🗸		\$	864.00
Floors	Repair defective	n/o [l Va	s 🗸			1,000.00
Other	Repair defective	n/a _	Υe	S		\$	1,000.00
		n/a 🗌	Υe	s 🗌		\$	
		n/a	Υe	s 🗌		\$	
		n/a 🗌	Υe	s 🗌		\$	
		n/a	Υe	s 🗌		\$	
					Interior: Estimated Cost:	\$	12,597.00
					Total Exterior and Interior Cost:*	\$	33,123.00

Inspected by: Tom Frank Date: 2/4/13

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.